


Instruction for Cat.6A STP Plug

1. Remove Cable' Jacket




2. Cut 2/3 Cable's Braid



3. Cut foil for 4 Pair Wires




4. After arrangement, cut 2mm away




Remark: Cut the wires with a scissors in a oblique angle. It will be easier to insert the wires into loading bar.

5. Put Wires into Insert




6. Cut the Balance Wires



7. Assemble Plug



8. Crimping Plug



Remark: According to FCC standard, $H=6.02\pm 0.13M$

9. Molding

